


Comparative Analysis of Hazard and Operability Study (HAZOP) and Systems Theoretic Process Analysis (STPA)

Faisal Jamal


Manager - Corporate HSE & TS, Fatima Fertilizer Company Limited, Pakistan


Dr. John P. Thomas

Scientist - Department of Aeronautics and Astronautics, MIT, USA




- Fatima Fertilizer Company Limited (FFL) - Fatima Group's flagship manufacturing facility. Annual fertilizer production 1.3 MT.
- DuPont Process Safety Management (PSM) Excellence Level-4. More than 55 Million man-hours without a Lost Time Injury (LTI).
- An endeavor to establish a comparison between STPA and current and established risk assessment techniques in the process industry - HAZOP.
- Looked at past 30 years' incidents in Ammonia plants using published info.
- Selected the complex CO₂ Removal System - includes human, machine and software interactions.
- This system's HAZOP was conducted by an experienced and qualified team maintaining high quality as per HAZOP methodology.
- An incident occurred on this HAZOP-ed system due to a missing control logic - not identified during HAZOP.






Nomenclature


- DCS: Distributed Control System (Human + Software)
- TI: Temperature Indicator
- PI: Pressure Indicator
- LI: Level Indicator
- LAL: Level Alarm Low
- LAH: Level Alarm High
- GLG: Glass Level Gauge
- FIC: Flow Indicator and Controller
- HPDA: High Pressure Differential Alarm
- PDI: Pressure Differential Indicator
- I: Interlock (Software for safe shutdown)
- Manual valve and local indicator (Human dependent)



- Foaming in CataCarb solution observed causing excessive and repeated carryover of solution to Methanator.
- Methanator temperature increased to 960°F (515°C) and the Methanator inlet valve HV-25 closed immediately as per control logic.
- However, this also cut the downstream seal gas flow towards the Cold box expander.
- Cold box expander process gas broke through from HP drain to oil console causing console over pressurization and consequently hydrogen fire.

Incident Description






Methanator Selector Switches & Discontinuation of Seal Gas flow caused cold process gas ingress to sour oil return towards oil console

1. Control logic modified to automatically trip Cold box expander on:
 - Methanator inlet valve HV-25 closure
 - Differential Pressure across seal gas and HP seal oil $< 0.2 \text{ kg/cm}^2$
 - Differential Pressure across seal gas and expander casing drops below 0.1 kg/cm^2
2. Installed a degasifying tank at sour oil HP drain line to avoid oil console over pressurization and consequent fire due to higher seal gas venting.

Safe and smooth plant operation after trip logic and other relevant modifications


- The experienced team did everything as required by the HAZOP methodology, but the requirement was missed.
- Petrochemical/refining processes are complex in nature and there is always a possibility of missing out any critical logic due to nodes/guidewords analyses.

Let's try STPA!




UCA

	NP	P	TE/LE	SIS/ATC
AVP	<p>DCS does not provide correct level for Lgt (LAH)</p> <p>DCS does not provide clear call out for Lgt (LAH)</p>	<p>DCS does not provide correct level for Lgt (LAH)</p> <p>DCS does not provide clear call out for Lgt (LAH)</p>	<p>DCS provides clear call out for Lgt (LAH)</p> <p>DCS provides clear call out for Lgt (LAH)</p>	<p>DCS provides clear call out for Lgt (LAH)</p> <p>DCS provides clear call out for Lgt (LAH)</p>
om	<p>DCS does not provide correct level for Lgt (LAH)</p> <p>DCS does not provide clear call out for Lgt (LAH)</p>	<p>DCS does not provide correct level for Lgt (LAH)</p> <p>DCS does not provide clear call out for Lgt (LAH)</p>	<p>DCS provides clear call out for Lgt (LAH)</p> <p>DCS provides clear call out for Lgt (LAH)</p>	<p>DCS provides clear call out for Lgt (LAH)</p> <p>DCS provides clear call out for Lgt (LAH)</p>






DCS	NP	P	TE/LE	SIS/ATC
DCS	DCS does not provide correct level for Lgt (LAH)	DCS does not provide clear call out for Lgt (LAH)	DCS provides clear call out for Lgt (LAH)	DCS provides clear call out for Lgt (LAH)




- Possible scenarios
- Missing FD LAH in Lgt
 - incorrect LAH indication
 - CA flow - DCS not providing clear call out for Lgt (LAH)







Losses to prevent




Model

Behavior to prevent




How could behavior occur




Nomenclature

- DCS: Distributed Control System (Human + Software)
- TI: Temperature Indicator
- PI: Pressure Indicator
- LI: Level Indicator
- LAL: Level Alarm Low
- LAH: Level Alarm High
- GLG: Glass Level Gauge
- FIC: Flow Indicator and Controller
- HPDA: High Pressure Differential Alarm
- PDI: Pressure Differential Indicator
- I: Interlock (Software for safe shutdown)
- Manual valve and local indicator (Human dependent)



DCS/PLC Controls


Human Controls



Nomenclature


- DCS: Distributed Control System (Human + Software)
- TI: Temperature Indicator
- PI: Pressure Indicator
- LI: Level Indicator
- LAL: Level Alarm Low
- LAH: Level Alarm High
- GLG: Glass Level Gauge
- FIC: Flow Indicator and Controller
- HPDA: High Pressure Differential Alarm
- PDI: Pressure Differential Indicator
- I: Interlock (Software for safe shutdown)
- Manual valve and local indicator (Human dependent)


Human Controls Feedback



Nomenclature

- DCS: Distributed Control System (Human + Software)
- TI: Temperature Indicator
- PI: Pressure Indicator
- LI: Level Indicator
- LAL: Level Alarm Low
- LAH: Level Alarm High
- GLG: Glass Level Gauge
- FIC: Flow Indicator and Controller
- HPDA: High Pressure Differential Alarm
- PDI: Pressure Differential Indicator
- I: Interlock (Software for safe shutdown)
- Manual valve and local indicator (Human dependent)






A simpler diagram

HV-25 Close
Cmd

Expander Trip
Cmd

Physical Process



Control Action	Not providing causes hazard	Providing causes hazard	Too early, Too late, Order	Stopped too soon, Applied too long
Close	UCA-1: PLC does not provide Close HV-25 Cmd when actual liquid level is high in the Absorber. [SH-2, SH-3, SH-4]	UCA-2: PLC provides Close HV-25 Cmd when actual liquid level in absorber is normal (cause Methanator trip). [SH-4] UCA-3: PLC provides Close HV-25 Cmd while expander remains in service (causes low seal gas flow to expander which will eventually result in fire) [SH-1,SH-2,SH-4]	UCA-4: PLC provides Close HV-25 Cmd too early when liquid level is high (trip set point) [SH-4] UCA 5: PLC provides Close HV-25 Cmd too late when liquid level in absorber is high (causes solution carryover to Methanator causing run away of reaction which will lead to Methanator vessel failure) SH-1,SH-2,SH-4]	UCA-6: PLC continues providing Close HV-25 Cmd too long after liquid level is normal (will prevent startup when issue is resolved) UCA-7: PLC stops providing Close HV-25 Cmd too soon before valve has fully closed UCA-8: PLC stops providing Close HV-25 Cmd too soon before liquid level in absorber has returned to normal
Open	[...]	[...]	[...]	[...]

Control Action	Not providing causes hazard	Providing causes hazard	Too early, Too late, Order	Stopped too soon, Applied too long
Close	[...]	[...]	[...]	[...]
Open	UCA-17: Operator does not provide Open HV-25 Cmd during startup [SH-3, SH-4]	UCA-18: Operator provides Open HV-25 Cmd when liquid level is high [SH-2, SH-4]	UCA 19: Operator provides Open HV-25 Cmd too soon during startup (causes quick pressurization of Methanator will result in leakage, catalyst damage, etc.) [SH-1, SH-2, SH-3, SH-4] UCA 20: Operator provides Open HV-25 too late during startup [SH-2, SH-4]	UCA-21: Operator continues providing Open HV-25 Cmd too long when liquid level is high [SH-2, SH-4] UCA 22: Operator provide Open HV-25 Cmd too soon during startup which cause high CO2 slippage enter Methanator and will cause temperature run away. [SH-1, SH-2, SH-3, SH-4]

Unsafe Control Action

Controller Requirement

UCA-1: DCS does not provide Close MV-25 cmd when actual liquid level in absorber is too high



R-UCA1: DCS shall provide Close MV-25 cmd when actual liquid level in absorber is too high (LAH=true) [**UCA-1**]

UCA-3: DCS provides Close MV-25 cmd too late (>10 sec) after liquid level in absorber is too high




R-UCA3: DCS shall provide Close MV-25 cmd within <10 sec of liquid level in absorber too high [**UCA-3**]

UCA-6: DCS provides Open MV-25 cmd when liquid level in absorber is too high



R-UCA6: DCS must not provide Open MV-25 cmd while liquid level in absorber is too high [**UCA-6**]




UCA-3: Operator does not manually trip Expander C-103 when HV-25 is closed (causes low seal gas flow to expander which will eventually result in fire) [SH-1,SH-2,SH-4]

CA-1: Tripping expander in case of HV-25 closure not effectively learned as a procedure (missing procedure, inadequate training for this procedure, conflicts with experience, etc.)

PM-1: Operator busy in emergency handling and forgets to trip expander

PM-2: Operator believes expander is already tripped automatically


FB-1: Missing alert/warning indicating HV-25 closed without expander trip (fire danger)
FB-2: RMP signal are not visible to operator on DCS
FB-3: Incorrect pressure reading for seal gas



Control
Actions

Feedback


Controlled Process



UCA


	NP	P	TE/LE	SDS/ATC
AVB	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication
CA	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication
AM	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication

- likely level
- R-1: DES not provide clear cut indication
 - R-2: DES not provide clear cut indication
 - R-3: DES not provide clear cut indication



loc	NP	P	TE/LE	SDS/ATC
loc	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication	DES does not provide clear cut indication

- Possible scenarios
- missing FD LAM in LogA
 - incorrect LAM indication
 - CA flow - DES not directly connected with LAM



At the time of detailed engineering of Catacarb unit, **the potential Hazard was not anticipated** against the HAZOP guide word of **no flow** to expander. Similarly **the consequence was not captured during HAZOP** under Methanator upstream valve closure **due to two separate nodes**.

Therefore, it may be concluded that this specific and well recognized technique “HAZOP” may be limiting in capturing all the hazards even if applied as per defined methodology/guideline.

However, STPA did result in identifying the missing control logic.

